Gouda Photo Report















Entrance to site via R44















Existing water crossings towards the site – these will not be impacted in any way







