

Steyn Borrow Pit Photo Report

Mining Area and surrounds





Approved spoil site



Powerlines

11kV next to application area



High Voltage line on the farm



Vegetation on site



Mountain Aloe



Water pipeline adjacent to application area



Existing excavation containing water adjacent to application area



Existing access roads



Existing excavation

